

**Flood Control Project Maintenance  
Levee Inspections  
Levee Log Report By Levee Mile - Updated 8/23/2021**

**Sutter Maintenance Yard Nelson Bend**

Waterway	Bank	Unit Miles	Inspector
Unit No. 01 Feather River West Levee - Nelson Bend		0.50	Dustin Sanoski

Entry No	Levee Mile		Category	Item	Location	Comment	Source
	Start	End					Permits
1	0.00	0.00	Mark	Boundary	Crown	Right bank levee of the Feather River at the southern end of Nelson Bend Weir. Mileage runs downstream. Entry Last Updated : 4/25/2017	H_LL_GENERAL
3	0.00	0.00	Revetment	Rock	Water Side	Waterward levee slope is rock revetted. Entry Last Updated : 4/25/2017	GEILEVEELOG
9	0.01	0.08	Fence	Barbed Wire	Water Side	Barbed wire fence on W S slope . Entry Last Updated : 5/24/2017	LEVEELOG
4	0.01	0.01	Gate	Metal	Crown	A landowner has constructed a gate on the crown that prevents inspection of this unit. The unit was inaccessible for the fall 2012 season and was not inspected. The unit was accessible during the spring 2013 inspection, but was difficult to open and should be monitored. Entry Last Updated : 10/18/2019	LEVEEINSPECTION
2	0.01	0.01	Ramp	Ramp	Water Side	Ramp on waterward slope. Access Sutter Bypass upstream of Nelson Bend Weir. Entry Last Updated : 4/25/2017	GEILEVEELOG
10	0.01	0.01	Non-Project Levee	Spur	Land Side	Wing levee on LS. Entry Last Updated : 5/24/2017	LEVEELOG
5	0.08	0.08	Revetment	Rock	Water Side	Bank is rock revetment. Entry Last Updated : 4/25/2017	H_LL_GENERAL
6	0.45	0.45	Ramp	Ramp	Land Side	Ramp on landward slope. Entry Last Updated : 5/24/2017	GEILEVEELOG
7	0.45	0.49	Structure	Building	Crown	Entry Last Updated : 10/18/2019	LEVEEINSPECTION
8	0.49	0.49	Mark	Boundary	Crown	End of levee. Entry Last Updated : 4/25/2017	H_LL_GENERAL